

BENEFITS

**Return lost capacity to
your used batteries**

**Full health report on
each battery**

**Keep your battery in
sulfate-free condition**

**Maximize battery
life-span**

**Save money on new
batteries**

**CONTACT US TODAY
FOR A QUOTE**



Call Us

330-468-4900



Email Us

fleetdispatch@burnslift.com



Visit Us

www.burnslift.com

Burns Industrial Equipment

8155 Roll & Hold Parkway
Macedonia, OH 44056

**REGENERATE
YOUR BATTERIES**



Increase Runtime

Extend Battery Life

Decrease Your Costs


SULFATION

What is Sulfation?

Sulfation, the accumulation of hard lead sulfate crystals, is the main reason for capacity and efficiency loss in lead-acid batteries. Sulfate crystals can develop rapidly, preventing your batteries from accepting a full charge.

How Does Sulfation Cost You Money?

Over time, sulfation crystals rob battery capacity. As a result, the battery needs more charge more often with a shorter runtime. As sulfation increases, so does your need to replace your batteries. Desulfate to reduce costs.



This represents sulfation over time

Advanced Technology


Battery Health Reports

A detailed health report is provided for each individual battery. We will provide your battery's performance both before and after the regeneration process.

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	Sum	Avg
00:00	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	39.60	2.20
00:03	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	2.2	39.60	2.20
00:06	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	2.19	39.42	2.19
00:09	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	39.25	2.18
00:12	2.18	2.18	2.18	2.18	2.18	2.18	2.14	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	2.18	39.20	2.18
00:15	2.17	2.17	2.17	2.17	2.17	2.17	2.14	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	39.03	2.17
00:18	2.17	2.17	2.17	2.17	2.17	2.17	2.14	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	2.17	39.03	2.17
00:21	2.16	2.16	2.16	2.16	2.16	2.16	2.14	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	38.86	2.16
00:24	2.16	2.16	2.16	2.16	2.16	2.16	2.14	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	2.16	38.86	2.16
00:27	2.15	2.15	2.15	2.15	2.15	2.15	2	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	38.55	2.14
00:30	2.15	2.15	2.15	2.15	2.15	2.15	2	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	2.15	38.55	2.14
00:33	2.14	2.14	2.14	2.14	2.14	2.14	2	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	38.38	2.13
00:36	2.14	2.14	2.14	2.14	2.14	2.14	1.89	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	2.14	38.27	2.13
00:39	2.13	2.13	2.13	2.13	2.13	2.13	1.85	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	38.06	2.11
00:42	2.13	2.13	2.13	2.13	2.13	2.13	1.75	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	2.13	37.96	2.11
00:45	2.12	2.12	2.12	2.12	2.12	2.12	1.6	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	37.64	2.09
00:48	2.12	2.12	2.12	2.12	2.12	2.12	1.6	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	2.12	37.64	2.09
00:51	2.11	2.11	2.11	2.11	2.11	2.11	1.6	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	37.47	2.08
00:54	2.11	2.11	2.11	2.11	2.11	2.11	1.6	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	2.11	37.47	2.08
00:57	2.1	2.1	2.1	2.1	2.1	2.1	1.6	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	37.30	2.07
00:60	2.1	2.1	2.1	2.1	2.1	2.1	1.6	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	2.1	37.30	2.07



One-Time Regeneration



Yearly Maintenance Regeneration

